

## Machinist Files - Half Round Files

These files are used for filing out concave surfaces and crevices, and for rounding out holes. The spiral cut enables them to remove metal rapidly and leaves a smooth finish.



EDP	Name	Length	Width	Thickness	Cut	
11150	Half Round	4	13/32	3/32	Bastard	<a href="#">Request Info</a>
11151	Half Round	4	13/32	3/32	Second	<a href="#">Request Info</a>
11152	Half Round	4	13/32	3/32	Smooth	<a href="#">Request Info</a>
11020	Half Round File 6	19/32	5/32		Bastard	<a href="#">Request Info</a>
11021	Half Round File 6	19/32	5/32		Second	<a href="#">Request Info</a>
11022	Half Round File 6	19/32	5/32		Smooth	<a href="#">Request Info</a>
11023	Half Round File 8	3/4	7/32		Bastard	<a href="#">Request Info</a>
11024	Half Round File 8	3/4	7/32		Second	<a href="#">Request Info</a>
11025	Half Round File 8	3/4	7/32		Smooth	<a href="#">Request Info</a>
11026	Half Round File 10	15/16	9/32		Bastard	<a href="#">Request Info</a>
11027	Half Round File 10	15/16	9/32		Second	<a href="#">Request Info</a>
11028	Half Round File 10	15/16	9/32		Smooth	<a href="#">Request Info</a>
11029	Half Round File 12	1-1/8	11/32		Bastard	<a href="#">Request Info</a>
11030	Half Round File 12	1-1/8	11/32		Second	<a href="#">Request Info</a>
11031	Half Round File 12	1-1/8	11/32		Smooth	<a href="#">Request Info</a>
11032	Half Round File 14	1-9/32	13/32		Bastard	<a href="#">Request Info</a>
11033	Half Round File 14	1-9/32	13/32		Second	<a href="#">Request Info</a>