


MTS Parallel Machine Reamers

Codes
711, 712



REAMERS,
COUNTERSINKS &
COUNTERBORES



d		l ₂	l ₁	Code	d		l ₂	l ₁	Code
mm	inch				mm	inch			

No. 1 Morse Taper Shank

3.0		32	115	7110300	8.731	11/32	62	142	7120873
3.175	1/8	32	115	7120318	9.0		62	142	7110900
3.5		32	115	7110350	9.5		62	142	7110950
3.969	5/32	32	115	7120397	9.525	3/8	66	146	7120953
4.0		38	120	7110400	10.0		66	146	7111000
4.5		38	120	7110450	10.319	13/32	66	146	7121032
4.762	3/16	38	120	7120476	10.5		66	146	7111050
5.0		38	120	7110500	11.0		71	151	7111100
5.5		45	127	7110550	11.112	7/16	71	151	7121111
5.555	7/32	45	127	7120556	11.5		71	151	7111150
6.0		45	127	7110600	11.906	15/32	76	156	7121191
6.350	1/4	50	130	7120635	12.0		76	156	7111200
6.5		50	130	7110650	12.5		76	156	7111250
7.0		54	134	7110700	12.700	1/2	76	156	7121270
7.144	9/32	54	134	7120714	13.0		76	156	7111300
7.5		54	134	7110750	13.494	17/32	81	161	7121349
7.900	5/16	50	130	7120794	13.5		81	161	7111350
8.0		58	138	7110800	14.0		81	161	7111400
8.5		58	138	7110850					

No. 2 Morse Taper Shank

14.288	9/16	81	181	7121429	19.0		93	193	7111900
14.5		81	181	7111450	19.050	3/4	100	200	7121905
15.0		81	181	7111500	19.5		100	200	7111950
15.081	19/32	87	187	7121508	19.844	25/32	100	200	7121984
15.5		87	187	7111550	20.0		100	200	7112000
15.875	5/8	87	187	7121588	20.5		100	200	7112050
16.0		87	187	7111600	20.638	13/16	100	200	7122064
16.5		87	187	7111650	21.0		100	200	7112100
16.668	21/32	87	187	7121667	21.431	27/32	107	207	7122143
17.0		87	187	7111700	21.5		107	207	7112150
17.462	11/16	93	193	7121746	22.0		107	207	7112200
17.5		93	193	7111750	22.225	7/8	107	207	7122223
18.0		93	193	7111800	22.5		107	207	7112250
18.256	23/32	93	193	7121826	23.0		107	207	7112300
18.5		93	193	7111850	23.019	29/32	107	207	7122302